

Republic of the Philippines Province of Negros Orcidental City of San Carlos

Telephone No. (034) 312-5205

		Eccepyo ne	320. (004) 01	12-2202					
					REQUEST FOR QUOTATION				
				36,600.00	REF. NUMBER	:	1314		
					DATE:		October 18, 2024		
					PURCHASE REQUEST NO.		1-24-09-1677		
					DATED:		September	18, 2024	
		Lot I			ABC:	IV		41,500.00	
		II	/	41,380.00	/	/ V		4,500.00	
		III	,	25,800.00	•	' VI		8,891.27	
						VII	-	2,988.40	
					BAC RES. NO.	NP-SVP	1393-24		
					DATED:		October 1	7. 2024	
								,	
					С	ITY MAYOR'S	OFFICE		
Gentlemen:									
Please quote your lowest price on the item/s listed below, subject to the General Conditions, stating									
the shortest time of delivery and submit your quotation duly signed by your representative.									
uic sii	or tost til	ne or delivery and submit your	quotation daily s	signed by you	ai representative	•	1/1		
								1	
					1	THE CONTRACT	PERADOMIA		
						MA. BRITAD. REBADOMIA			
					2400	CGADH I-PMSD cretariat & Procurement DivCMO(Reassigned			
					BAC Secretariat 8	& Procurement	DIVCMO(R	eassigned	
NOTE: 1. ALL ENTRIES MUST BE TYPEWRITTEN / HANDWRITTEN									
2. WARRANTY SHALL BE FOR A PERIOD OF SIX (6) MONTHS FOR SUPPLIES & MATERIALS,									
ONE (1) YEAR FOR EQUIPMENT, FROM DATE OF ACCEPTANCE BY PROCURING ENTITY									
3. PRICE VALIDITY SHALL BE FOR A PERIOD OF 120 CALENDAR DAYS									
4. ALL DELIVERIES MUST BE F.O.B. SAN CARLOS CITY, NEGROS OCCIDENTAL									
	5. PLEASE SUBMIT YOUR QUOTATION 7 CALENDAR DAYS UPON RECEIPT OF REQUEST FOR QUOTATION (RFQ)								
		(EXCEPT FOR GASOLINE & DIE							
ITEM						UNIT			
NO.	UNIT	IIEM & L	DESCRIPTION		QTY.	PRICE	TOT	AL	
110.		Lot I:For Toyota Hilux SAA 7	151			1			
1	piece	Disc, Front	101		2				
2			ont I LI		1				
		Absorber Assembly, Shock,Fr							
3	piece	Absorber Assembly, Shock,Fr			(1				
			yota Hilux S4F	801					
1		Rotor Disc, Front			2				
2	piece	Absorber Assembly, Shock, F	ront LH		1				
3		Absorber Assembly, Shock, F			11				
	P.O.O.O.	Lot III:For Toyota FX P7 X00	5			-			
1	niece	Rotor Disc, Front			2				
1	piece		0		4				
		Lot IV:For Toyota FX P9 J03	9						
1		Rotor Disc, Front	2.2.22		1/1				
2		Absorber Assembly, Shock, F							
3	piece	Absorber Assembly, Shock, F	1						
		Lot V:For Toyota Hi Ace Cor	nmuter S4J07:	2					
1	piece	Element Sub-Assy., Air Cleane			1				
2		Air Filter			1				
-	Picco	Lot VI:For Toyota Hilux Con	nuest P21723						
1	niece	Oil Filter IMV	440011 21/20		1				
2		Gasket			1				
3		5W-30 1L			8		-		
4		Window Washer Fluid	/		1				
5		DSL Injector Cleaner			A				
6		Genuine Brake Cleaner			2				
7		Waste Rags			2				
8		Sand Paper			2 2 2				
9	piece				1				
9	hiere	Lot VII:For Toyota Hilux Cor	10110ct D24722				-		
4	oon in		quest F21/23		4				
1	service	50,000 KM Check up)	1				
			·x-x-x-x-x	/	/				
		Delivery Term:15 Working D	ays						
For use of the service vehicles Toyota Hilux SAA 7151, Toyota Hilux S4 F801, Toyota FX P7 X005, Toyota FX P7								ota FX /	
PURPOSE For use of the service vehicles Toyota Hilux SAA 7151, Toyota Hilux S4 F801, Toyota FX P7 X005, Toyo									
17 0 0000, Toyota Committee Fill 700 04 0072 & Toyota Fillax Conquest 121720 of the Oily Mayor 3 Office.									
After having carefully read and accepted your General Conditions, I/We quote you on the item/s at									
prices noted above.									
priods floted above.									
Printed Name/Signatur									
						rinted Nati	neroignature		
0.11		274							
CANV	ASSED E		r.						
		Printed Name/Signature	Tel.I	Tel.No./Cellphone No./E-Mail Address					

Date